

TECH TIP

ROTAX
RACING

02 Multiple Function Switch Update

1 - MULTIPLE FUNCTION SWITCH

Grease isolating the contacts, inside the switch, causing the failure. (engine start problems, possible engine misfire)

Procedure to fix a failed switch:

- › Replace defective switch with a new switch:
New switch must be marked with the number "264854".
- › Removal of grease from the connector
The removal of grease is only valid for the connector of the switch, not for any other connector of the wiring harness!



2 - SWITCH SEALING

The switch must not be opened!

- › The switch is sealed on the parting line to prevent water intrusion.
- › By opening the switch this will break the sealing which can cause failure and warranty becomes void.



3 - RECOMMENDED CLEANING PRODUCTS

Contact Cleaner
(e.g. Spraywash)

Brake Cleaner
(e.g. XPS)

