



BULLETIN

From:	The Stewards	Bulletin No:	3.03
To:	DD2 Masters Competitors	Date:	3rd December 2023
	All Officials	Time:	16:00 hrs

The Stewards notify all competitors and officials of the following:

Corrections to RNCGF 2023 Technical Regulations:

I. 125 MAX DD2 Masters – Charles Leclerc

No.	Item	Specification
1	Carburation and gearing mandatory for the 1 st free practice.	134 Main Jet must be installed. Gear ratio set 36 / 61 Please note: you will need to install the correct main jet
2	Carburation and gearing options for the 2 nd free practice through to the Finals	Any main jet from the kit supplied can be used. (128, 129, 130, 131, 132, 133, 134, 135, 136, 137 & 138) Gear ratio sets (36 / 61), (35 / 62) or (34 / 63 in combination with wet tyres only)
3	Spark plug type and gap	NGK GR8DI. Filler gauge 1,00 mm must not fit in between the two electrodes.
4	Ride height	Modify the height of the frame in the front (only possible to go up with the chassis)
5	Camber and Castor	0 / 0,5 / 1,5 degrees
6	Ackerman settings	As supplied or with steering column number 2
7	Seat supports	Maximum 2 on the left and 1 on the right
8	Seat fixing	The 2 seat screws from the bottom can be loosed
9	Rear bumper	It is possible to loosen the rear pods, can only move vertically.
10	Wheel base	1045 mm
11	Other notes	Removing the front bar stabilizer (or in or out) is allowed
12	Steering	Allowed a steering column 520mm long. Allowed an additional plastic shim with a an angle of 10 degrees for changing the steering wheel angle

[Bulletin continued on page 2]

Supported by:

#MOJO®

XPS

BELL HELMETS

SODI

CHARLES LECLERC

Praga

DELTA

WIPAC

© 2023 BRP-Rotax GmbH & Co KG. All rights reserved. ® and TM and the BRP logo are trademarks of Bombardier

Valter Fernandes
Chairman Steward Gr.3
Lic.No.CDI PT23/2857
2023-12-03 17:02

Ken Potter
Stewards Board Gr.3
Lic.No.CDI PT23/2857
2023-12-03 17:02

ts. All other trademarks are the property of their respective owners.



From the 2nd non-qualifying practice ROTAX recommends: Jet 132, needle position 4, 0,65mm spark plug gap and 55°C engine temperature

Note: Only standard components as supplied at the event by the manufacturer for the specific category may be used in accordance with the RMCGF Technical Regulations 2023 and its appendices.

Valter Fernandes (PRT)
Steward (Chairman)

Ken Potter (UK)
Steward

Jawad Derbas (BH)
Steward

Supported by:

#MOJO®

XPS

BELL
HELMETS

SODI

Valter Fernandes
Chairman Steward Gr.3
Lic.No.CDI PT23/2857
2023-12-03 17:02

Ken Potter
Stewards Board Gr.3
Lic.No.230237
2023-12-03 17:02

HARVEY
MILLER

Praga

DELORIO

WIPAC

© 2023 BRP-Rotax GmbH & Co KG. All rights reserved. ® and TM and the BRP logo are trademarks of Bombardier

ts and all other trademarks are the property of their respective owners.